## **Environmental Protection Agency**

- (2) Specifications for the sensor, signal analyzer, and data collection system.
- (3) A monitoring schedule that specifies the frequency that the parameter values will be determined and recorded.
- (4) The operating limits for each parameter that represent continuous compliance with the emission limitations in §63.9788, based on values of the monitored parameters recorded during performance tests.
- (5) Procedures for installing the CPMS at a measurement location relative to each process unit or APCD such that measurement is representative of control of emissions.
- (6) Procedures for the proper operation and routine and long-term maintenance of each process unit and APCD, including a maintenance and inspection schedule that is consistent with the manufacturer's recommendations.
- (7) Procedures for the proper operation and maintenance of monitoring equipment consistent with the requirements in  $\S 63.8(c)(1)$ , (3), (4)(ii), (7), and (8), and 63.9804.
- (8) Ongoing data quality assurance procedures in accordance with the general requirements of §63.8(d).
- (9) Procedures for evaluating the performance of each CPMS.
- (10) Procedures for responding to operating parameter deviations, including the procedures in paragraphs (a)(10)(i) through (iii) of this section:
- (i) Procedures for determining the cause of the operating parameter deviation.
- (ii) Actions for correcting the deviation and returning the operating parameters to the allowable limits.
- (iii) Procedures for recording the times that the deviation began and ended, and when corrective actions were initiated and completed.
- (11) Procedures for keeping records to document compliance and reporting in accordance with the requirements of §63.10(c), (e)(1), and (e)(2)(i).
- (12) If you operate a kiln that is subject to the limits on the type of fuel used, as specified in items 3 and 4 of Table 3 to subpart SSSSS, procedures for using alternative fuels.
- (13) If you operate an affected continuous kiln and you plan to take the kiln

- control device out of service for scheduled maintenance, as specified in §63.9792(e), the procedures specified in paragraphs (a)(13)(i) and (ii) of this section
- (i) Procedures for minimizing HAP emissions from the kiln during periods of scheduled maintenance of the kiln control device when the kiln is operating and the control device is out of service.
- (ii) Procedures for minimizing any period of scheduled maintenance on the kiln control device when the kiln is operating and the control device is out of service.
- (b) Changes to the operating limits in your OM&M plan require a new performance test. If you are revising an operating limit parameter value, you must meet the requirements in paragraphs (b)(1) and (2) of this section.
- (1) Submit a Notification of Performance Test to the Administrator as specified in §63.7(b).
- (2) After completing the performance tests to demonstrate that compliance with the emission limits can be achieved at the revised operating limit parameter value, you must submit the performance test results and the revised operating limits as part of the Notification of Compliance Status required under §63.9(h).
- (c) If you are revising the inspection and maintenance procedures in your OM&M plan, you do not need to conduct a new performance test.

## TESTING AND INITIAL COMPLIANCE REQUIREMENTS

## § 63.9796 By what date must I conduct performance tests?

You must conduct performance tests within 180 calendar days after the compliance date that is specified for your source in §63.9786 and according to the provisions in §63.7(a)(2).

## § 63.9798 When must I conduct subsequent performance tests?

(a) You must conduct a performance test every 5 years following the initial performance test, as part of renewing your 40 CFR part 70 or 40 CFR part 71 operating permit.